Work Order ID 102117 Page 1 May-27-13 12:39:24 PM D3265-041 Accept Item ID: *N900040100* Setup Start **Revision ID:** Item Name: Basket Base Assembly Start Qty: 1.00 *1* Start Date: 5/27/13 Cust Item ID: Required Date: 5/27/13 Reg'd Oty: 1.00 Customer: Reference: Run Date: /3-05-27 Tooling: Process Plan: MC5 Date: Approvals: Stop SPC (Y/N): QC: Date: Sequence ID/ Operation Set Up/ Tool ID Tool # Plan Reject Reject Accept Insp. Work Center ID Description Code Qty Qty Number Stamp **Run Hours** Draw Nbr **Revision Nbr** Е D3265 Weld per dwg A/R S.S. rod Batch: R123823 100 Large Fab *100* CC 13-8-77 0.00 Large Fab Memo 1- Assemble and weld as per Dwg D3265 using DT9444 Large Fab 2- Deburr and remove all markings from material as required 3- weld mesh as per dwg

110

QC9- Inspect visual per QSI004- Fusion Welds

p(13.828)

110 QC

Memo

0.00

Quality Control

NCR: Ye	es / No				WORK ORDER NON-C	ONFO	RMANCE / UI	PDATE			
	-						•		QA Closed:	Date	:
	r:				DISPOSITION			AGAINST DE	PARTMENT	/PROCESS	
Part N		-			Rework Scrap		Skid-tube Machining	Crosstube Small Fab	Pro	Water Jet	Engineering Quality
NCR N	o				Use-as-is Work Order Update	The	ermoforming Large Fab	FinishingComposite	Rec/Sto	re/Packaging Supplier	Other
Root			[Descri	ption of work order update	Initia	A	ction	Sign &	1	
Cause	Date	Step	Qty		or Non-conformance	Chief E	ng Des	cription	Date	Verification	QC Inspector
Doc/Data											
Equip/Tooling											
Operator		İ									
Material									1		
Setup											
Other											
Process	_										
Supplier	4										
Training	\dashv										İ
Unapproved		<u> </u>					TECONY		!	<u> </u>	<u> </u>
Landin	a Goar				General FA	AULI CA	TEGORY				
	Bending				Bend	Grai	n	Г	Ovalized		Pressure/Forced
F	Centre No	nt Concer	ntric to (n/s	BOM/Route	Hard		<u> </u>	Over/Under	tolerance	Temperature/Cure
-	Cracks	or correct	ine to t		Broken/Damaged	⊢	ection Incomplete	<u> </u>	Part Incorre	<u> </u>	Weld
<u> </u>	Crushed/	Crimped			Burrs	⊢	uctions Incomplete	/Unclear	Part Lost/Mi	-	Wrong Stock Pulled
ŀ	Cuffs	,			Contamination	⊢ ≓	ntenance	,	Part Moved		
<u> </u>	Heat Trea	ıt			Countersink	⊢ ⊢i	beled		Positioned V	Vrong	
	Inspection		Tube	-	Cut Too Short	Misr			Power Loss/	_	Other
	Ripples in	•			Drill Holes	Offse	et		- É	-	•
	Torque W	/aves in E	xtrusio	n 🗂	Drawing	Out	of Calibration				
Ţ	Turning S	equence			Finish	Out	of Sequence				

Outside Dimensions

DQA:

Date:

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

Wave/Twist in Tube

Folio

Work Orde <i>May-27-13 12:3</i>		2117		*102117*								Page 2			
Item ID: Revision ID: Item Name:	D3265-041 Basket Base A	ssembly		Accept	*N900	040 1	INN*	Se	etup Start	1.73	S1* S2*				
Start Date: Required Date: Reference:	5/27/13 5/27/13	Start Qty: 1.00 Req'd Qty: 1.00	*1 [*]		Cust Item I Customer:	D:									
Approvals:		in:	Date:	Tooling: SPC (Y/N):		ate:		Ri	un Start Stop	1/7	R1* R2*				
Sequence ID/ Work Center II 120 *120* QC Quality Control)	Operation Description QC6- Inspect dimension Memo	s to drawing	Set Up/ Run Hours 0.00 DAS 27 0.00 9-89	Tool ID		Plan Ac Code Qt	ecept y	Reject Qty	Reject Number	Insp. Stamp				
130 *120* Powdercoat Powder Coating	,	White Gloss(Ref:4.3.5.1 Memo 1ST COAT: START TIN OVEN TEM	1	1-30.00 1-40>01-			12)	¥1,	M-J	13-/0	1/2	<u></u>			

w/abla5

FINISH TIME: ****if necessary**** 2ND COAT: START TIME: OVEN TEMPERATURE: FINISH TIME:

NCR: Y	es / No				WORK ORDER NON-C	CON	FORN	//ANCE / UPI	DATE			
_								=	<u></u>	QA Closed:	Date:	
Work Orde	r :				DISPOSITION				AGAINST DI	PARTMENT	PROCESS	
Doet N					Rework			Skid-tube Aachining	Crosstube Small Fab	Pro	Water Jet d. Eng. Coor.	Engineering Quality
Part N	U				Scrap Use-as-is	1 I		noforming	Finishing	-	e/Packaging	Other
NCR N	o				Work Order Update	<u> </u>		Large Fab	Composite	, Kec/stoi	Supplier	
	 							Act	•	C: 0		
Root			۱		ption of work order update	1	itial			Sign &	1 / a wifi a a Ai a a	061
Cause	Date	Step	Qty	•	or Non-conformance	Chie	ef Eng	Descr	ription	Date	Verification	QC Inspector
Ooc/Data	_	ĺ										
quip/Tooling												
perator	\dashv											
Material .	-		1									
etup Other	-											
rocess	\dashv											
upplier	\dashv	1										
raining	┪											
Inapproved	1											
1					F	AULT	CATE	GORY		<u> </u>	·	L
Landin	g Gear				General			_				
[Bending				Bend		Grain			Ovalized		Pressure/Forced
Ī	Centre I	Not Conce	ntric to	o/s	BOM/Route	\square	lardwa	re		Over/Under	tolerance	Temperature/Cure
[Cracks				Broken/Damaged		nspecti	on Incomplete		Part Incorred	it	Weld
	Crushed	/Crimped			Burrs	i i	nstruct	ions Incomplete/U	Jnclear	Part Lost/Mi	ssing	Wrong Stock Pulled
, [Cuffs				Contamination		Mainte	nance		Part Moved		
[Heat Tro	eat			Countersink		√lislabe	led		Positioned V	/rong	_
	Inspecti	on Strip in	Tube		Cut Too Short		Misread	l		Power Loss/	Surge	Other
	Ripples	in Bend			Drill Holes		Offset					
Ī	Torque	Waves in I	Extrusio	n [Drawing		Out of C	alibration				
	Turning	Sequence	:		Finish ,		Out of S	equence				
	Wave/T	wist in Tu	be		Folio		Outside	Dimensions				

DQA:

Date:

H:/FORMS/Quality Assurance\approved_QA/NCRWO Rev G

0.00

Memo

Quality Control

											DQA:	Date:	
NCR:	'es	/ No				WORK ORDER NON-	COI	NFORM	MANCE / UPI	DATE	QA Closed:	Date:	
						DISPOSITION				AGAINST DE			-
Work Orde	er:						٦				ī	14/a4 a 1 1 a 4	3 -
Part i	lo.					Rework Scrap Use-as-is			Skid-tube Machining noforming	Crosstube Small Fab Finishing	-	Water Jet d. Eng. Coor. re/Packaging	Engineering Quality Other
NCR N	lo.		<u></u>			Work Order Update			Large Fab	Composite]	Supplier	
Root						iption of work order update		Initial		ion	Sign &		0.51
Cause		Date	Step	Qty		or Non-conformance	- Cr	nief Eng	Descr	ription	Date	Verification	QC Inspector
oc/Data													
quip/Tooling Operator		,											
Aaterial													
etup.													
other 🔭													
rocess					i							,	
upplier				1									İ
raining													
Inapproved													
							FAUL	T CATE	GORY				· · · · · · · · · · · · · · · · · · ·
Landi	ng (Sear				General	_	,			7	_	_
		Bending			L	Bend		Grain			Ovalized		Pressure/Forced
		Centre No	ot Concei	ntric to	O/S	BOM/Route	_	Hardwa		<u> </u>	Over/Under		Temperature/Cure
	<u> </u>	Cracks			_	Broken/Damaged	_	1 '	on incomplete		Part Incorred		Weld
	<u> </u>	Crushed/	Crimped		<u> </u>	Burrs	_	4	ions Incomplete/l	Jnclear	Part Lost/Mi	ssing	Wrong Stock Pulled
	_	Cuffs			-	Contamination	-	Mainte		_	Part Moved		
	<u> </u>	Heat Trea			-	Countersink	\vdash	Mislabe		\vdash	Positioned V		70.60
	<u> </u>	Inspection		fube	 -	Cut Too Short	\vdash	Misread	1		Power Loss/	Surge	Other
	\vdash	Ripples in			_	Drill Holes	-	Offset	*_1!!a!			.	
	<u> </u>	Torque W			n	Drawing	\vdash	4	Calibration				
	1	Turning S	equence		l	Finish	1	¡Out of 9	Sequence				į

Outside Dimensions

Wave/Twist in Tube

Folio

Work Ord May-27-13 12		02117	*102117*						
Item ID: Revision ID:	D3265-041		± 1	Accept	*N900040100*	Setup	Start Stop		
Item Name: Start Date: Required Date	Basket Base 5/27/13 e: 5/27/13	Start Qty: 1.00 Req'd Qty: 1.00	*1* *1*		Cust Item ID: Customer:				
Reference: Approvals:	Process P	lan:	Date:	Tooling: SPC (Y/N):	Date:	Run	Start Stop		

Identify as per dwg & Stock Location 0.50-60-70-80-45

Set Up/

0.00

0.00

0.00

Run Hours

Sequence ID/

170

*1 **A N** *

Quality Control

Packaging

Packaging

170

180

Work Center ID

Operation

Description

Memo

Memo

QC21- Final Inspection - Work Order Release

/ P 12 13 8-50.

Reject

Insp.

Number Stamp

Reject

Qty

Accept

Qty

Tool # Plan

Code

Tool ID

101862.

Page 4

Barle

										DQA:	Date:	
NCR: Y	es / No				WORK ORDER NON	N-CON	IFORMA	NCE / UPDA	TE	QA Closed:	Date:	
-					<u> </u>					- UA CIOSEU.	Date.	i.
Work Orde	<u>.</u>				DISPOSITION	•			AGAINST DE	PARTMENT	/PROCESS	
WOLK OLDE	·				Rework	┌	Skio	d-tube C	Crosstube	1	Water Jet	Engineering
Part N	0.				Scrap	— I			Small Fab	Pro	d. Eng. Coor.	Quality
					Use-as-is		Thermofo	- -	Finishing	Rec/Sto	re/Packaging	Other
NCR N	0				Work Order Update		Lar	ge Fab 🔃 C	omposite		Supplier	
					<u></u>					-		T
Root			1 1		iption of work order update		nitial	Action		Sign &		
Cause	Date	Step	Qty		or Non-conformance	Ch	ief Eng	Descripti	on	Date	Verification	QC Inspector
Ooc/Data												
quip/Tooling	_	}										
perator	4											
laterial	_						1					
etup	_					ļ	1					
Other		ļ				İ						
rocess	_	1	i									
upplier	╡											
raining Inapproved	\dashv											
mapproved [<u>. </u>	<u> </u>			FAUL	T CATEGOR			<u>.L</u>	<u></u> .	<u>. </u>
Landin	g Gear				General			<u> </u>				
Γ	Bending				Bend		Grain			Ovalized		Pressure/Forced
		ot Conce	ntric to O	/s	BOM/Route		Hardware			Over/Under	tolerance	Temperature/Cure
Ī	Cracks	Ţ			Broken/Damaged		Inspection I	ncomplete		Part Incorre	ct	Weld
[Crushed/	Crimped			Burrs		Instructions	Incomplete/Uncl	ear	Part Lost/Mi	ssing	Wrong Stock Pulled
Ī	Cuffs				Contamination		Maintenar	ice		Part Moved		
	Heat Trea	ət			Countersink		Mislabeled			Positioned V	Vrong	_
	Inspectio	n Strip in	Tube		Cut Too Short		Misread			Power Loss/	Surge	Other
[Ripples in	n Benjd		· [Drill Holes		Offset					
	Torque V	Vaves in I	Extrusion		Drawing		Out of Calib	ration			· · · · · · · · · · · · · · · · · · ·	
	Turning 9	Sequence	:		Finish		Out of Sequ	ience				
[Wave/Tv	vist in Tul	be		Folio	- 1	Outside Din	nensions				

Picklist Print

May-27-13 12:39:22 PM

Work Order ID:

102117

Parent Item:

D3265-041

Parent Item Name:

Basket Base Assembly

Start Date: 5/27/13

Required Date: 5/27/13

Start Qty: 1.00

Required Qty: 1.00

Comments:

IPP Rev:C Re-Format 05-11-03 JLM

IPP Rev:D 08-09-10 revC as per dwg (ecn 08-524) DD verf: by:EC IPP RevE: as per DEO DD

10.09.12 verified by:EC

IPP RevF: revise seq 110 DD 10.01.28 verified by:EC

IPP

_	REV:G 12.07.26	AS PER DWG RE	EV.D D	D_VERF:EC									F 12900 P12
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2232-3 Basket Hinge		Manufactured	No			100	Each	31.0000	2	2	//	13-8	<u>-27</u>
Dasket ringe				Location		Loc Oty	<u>Lo</u>	e Code			<i>'</i> ـــــ		
				WA			}						
				972	261	-	3		-				
				WA004		28	3						
				755	881	7	2						
				980		(5						
				984	173	20)		([X]_			
D2235-1		Manufactured	No			100	Each	11.0000	1	1	P	10	3 <u>-</u> 2}
Basket Rib											<u> </u>	152	5_2/
				Location		Loc Oty	<u>Lo</u>	c Code					
				WA004		1	R9828	س	<i>(</i>	IX)			
				668	895		01000	0 -					
				856	502	4	ļ						
				860	051		l						
				965	545	2	2						

NCR:	Yes	1	No
14011.	163	,	110

DQA: _____ Date: _____

NCR: Y	es /	No				WORK ORDER NON-	CON	FORN	MANCE / UPI	DATE	QA Closed:	Date	:
Work Orde	r·			· · · · · ·	·	DISPOSITION	\Box			AGAINST D	EPARTMENT,	/PROCESS	
Part N	-					Rework Scrap]		Skid-tube Machining	Crosstube Small Fab	Pro	Water Jet d. Eng. Coor.	Engineering Quality
NCR N	o					Use-as-is Work Order Update			noforming Large Fab	Finishing Composite	Rec/Stor	e/Packaging Supplier	Other
Root		_	-			iption of work order update		nitial		tion	Sign &) (E A	061
Cause	+	Date	Step	Qty		or Non-conformance	Chi	ief Eng	Desci	ription	Date	Verification	QC Inspector
oc/Data quip/Tooling	\dashv												
perator	\dashv						ł					-	
naterial													
etup	┪.												
ther	\dashv												
rocess	1												
upplier											Ì		
raining													
Inapproved			<u> </u>										
							AUL1	T CATE	GORY				
Landin	g Ge	ar				General				_	_	_	·
	B	ending				Bend	Ш	Grain		L	Ovalized		Pressure/Forced
L	c	entre No	ot Concer	ntric to	o/s	BOM/Route	\vdash	Hardwa			Over/Under	<u> </u>	Temperature/Cure
ļ	C	racks				Broken/Damaged	-		on Incomplete	<u>_</u>	Part Incorred	<u> </u>	Weld
	—		Crimped		<u> </u>	Burrs	\vdash		ions Incomplete/I	Unclear	Part Lost/Mi	ssing	Wrong Stock Pulled
	C	uffs				Contamination	\vdash	Mainte		ļ	Part Moved		
1	ᅴᅢ	eat Trea	it			Countersink	-	Mislabe		-	Positioned V		7
ļ	_	-	n Strip in	Tube	<u> </u>	Cut Too Short	-	Misread	i	L	Power Loss/	Surge	Other
	_	ipples in			L	Drill Holes	-	Offset					
		-	/aves in E		n L	Drawing	┅		Calibration				· · · · · · · · · · · · · · · · · · ·
Į		urning S	equence			Finish	-		equence				
	- Iv	/ave/Tw	ist in Tuk	e		Folio	+ 1	Outside	Dimensions				

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

May-27-13 12:39:22 PM

Work Order ID:

102117

Parent Item:

Mounting Bracket

D3265-041

Parent Item Name:

Basket Base Assembly

D2581

D3265-1

D3265-5

Rib

Rib

Manufactured

Manufactured

Manufactured

No

No

No

100

Each

60.0000

Start Date: 5/27/13

Start Qty: 1.00

Required Qty: 1.00

Required Date: 5/27/13

CC 13-8-27 Location Loc Oty Loc Code

WA	6 R103100 (2)	
98503	6 B10395Z -> (2x)	
WA004	$_{54}$ B103732 $(2x)$	
101383	20	
70766		
81253		
82506		
83230		
85452	2	
87706	2	
99067		
99837	10	

D3265-043	Manufactured	No	100	Each	2.0000	1	1 // /2-8-1-
Rib Assembly							
. **#		Location	Loc Qty		Loc Code		

WA004		2	
WA004		2	
_	100	Each	10.0000

Location	Loc Qtv		Loc Code	
WA005	2			
96745	2			(/x)
WA006	8			
51483	4			
55842	4			
	100	Each	8.0000	2 2 66 13-8-27

Location	Loc Oty Loc Code	
<i>₩</i> Α ,	8/04698 -> (Zx)	
96886	8	

|--|

DQA: _____Date: _____

NCR: Ye	es / N	ס			WORK ORDER NON-	-CONF	UKIV	MANCE / UPL	JAIC	QA Closed:	Date	: :		
Nork Ordo	·-				DISPOSITION		AGAINST DEPARTMENT/PROCESS							
Part No.					Rework Scrap		Skid-tube Crosstube Machining Small Fab			Water Jet Prod. Eng. Coor.		Engineering Quality		
NCR No.				Use-as-is Work Order Update	┪┃╹	Thermoforming Finishing Large Fab Composite			Rec/Stoi	re/Packaging Supplier	Other			
Root				Descr	ription of work order update		Initial Action			Sign &				
Cause	Dat	e Step	Qty	_	or Non-conformance	Chief	Eng	Descr	iption	Date	Verification	QC Inspector		
oc/Data quip/Tooling perator faterial	_													
etup														
ther														
rocess				ļ										
upplier							ŀ							
raining	╡	'	1				ļ				ļ			
Inapproved	1											-		
<u></u> 1.	•					FAULT C	ATEC	ORY						
Landin	g Gear				General					-				
[Bendi	ng			Bend	Gr	rain		<u></u>	Ovalized	L	Pressure/Forced		
	Centre	Centre Not Concentric to O/S			BOM/Route		Hardware			Over/Under tolerance		Temperature/Cure		
	Crack	Cracks			Broken/Damaged		Inspection Incomplete			Part Incorrect		Weld		
	Crush	Crushed/Crimped Burrs			Ins	Instructions Incomplete/Unclear			Part Lost/Missing Wrong Stock Pulled					
	Cuffs				Contamination	М	Maintenance			Part Moved				
	Heat Treat				Countersink	Mi	Misłabeled			Positioned Wrong				
	Inspec	tion Strip i	n Tube		Cut Too Short	Мі	Misread		L	Power Loss/	Surge	Other		
],	Ripple	s in Bend			Drill Holes	Of	fset							
[Torqu	e Waves in	Extrusio	n [Drawing	——————————————————————————————————————		alibration				<u></u>		
	Turnii	Turning Sequence - Finish				ou	it of S	equence	•					
	Wave/Twist in Tube Folio					Ou	ıtside	Dimensions						

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

May-27-13 12:39:23 PM

Work Order ID: 102117 Required Date: 5/27/13 Parent Item: D3265-041 Start Date: 5/27/13 Required Qty: 1.00 Start Qty: 1.00 Basket Base Assembly Parent Item Name: D3442-5 100 12.0000 No Each Manufactured C 13-8-27 Shim Loc Oty Loc Code Location WA 98414 WA004 33282 86836 D3825-041 100 10.0000 Manufactured No Each 2 CC_13-8-27 Rib Assembly (Basket End) Location Loc Qty Loc Code WA004 10 10 100 D3826-041 0.0000 No Manufactured Rib/Gusset Assembly 1.0000 D3832-11 100 No Manufactured CC 13-8-27 Mcsh (Base) Loc Oty Loc Code Location WA004 90140 D3833-1 No 100 Each 22.0000 CC_13-8-27 Manufactured Mesh (Base End Face) Loc Oty Loc Code Location WΛ 15 3 98359 12 WA007 77521 81259 89208 98538

											DQA:	Date:		
NCR:	Yes /	No				WORK ORDER NON	-CO	NFORM	MANCE / UPI	DATE				
											QA Closed:	Date:		
Work Order:						DISPOSITION	AGAINST DEPARTMENT/PROCESS							
WOIK OIG						Rework	Skid-tube Crosstube			7	Water Jet	Engineering		
Part I	No.					Scrap		Machining Small Fab			d. Eng. Coor.	Quality		
						Use-as-is	_	1	noforming	Finishing		re/Packaging	Other	
NCR I	No.					Work Order Update	コー		Large Fab	Composite	1	Supplier	i 🗆 🗖	
						• •				_	-			
Root					Descri	ption of work order update		Initial		tion	Sign &			
Cause		ate	Step	Qty		or Non-conformance	C	hief Eng	Descr	ription	Date	Verification	QC Inspector	
Doc/Data	Ш	1								•				
Equip/Tooling	Ш													
Operator	Ш	1												
Material	Ш	ŀ					İ							
Setup	Щ								•					
Other	Ш	1												
Process	Ш	1			7					i .				
Supplier	Ш													
Training	Ш					•								
Unapproved							<u>-</u>							
						 	FAU	LT CATE	GORY					
Landi	ng Gea				_	General	_	_		_	7	.	1 .	
	Bending					Bend	Grain		<u> </u>	Ovalized		Pressure/Forced		
	Centre Not Concentric to O/S					BOM/Route	}	Hardware			tolerance	Temperature/Cure		
	Cracks					Broken/Damaged	⊣	Inspection Incomplete			ct	Weld		
		ished/C	rimped		<u> </u>	Burrs	\perp	-	nstructions Incomplete/Unclear			ssing	Wrong Stock Pulled	
	Cui				<u> </u>	Contamination	Contamination Maintenance				Part Moved			
l	Heat Treat					Countersink Mislabeled					Positioned V	Vrong		

Misread

Out of Calibration

Out of Sequence

Outside Dimensions

Offset

Power Loss/Surge

Other

Ripples in Bend

Turning Sequence

Wave/Twist in Tube

Inspection Strip in Tube

Torque Waves in Extrusion

Cut Too Short


Drill Holes

Drawing


Finish

Folio


H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G











k 5-